



Thin IZM Wafers with Photoresist

150 micron. Region ground through to photoresist. Uneven coating?



200 micron. Cracked by me.
Notice patch of interaction with
UV tape



250 micron. Large
region of interaction
with UV releasing
tape.

